

Test Report	No.: SHHL1909051777FT	Date: SEP. 30, 2019	Page: 1 of 8
ZENITH INTERIORS (SHA	NGHAI) CO LTD		
L1, BLDN 2, 1788 HANGT	ANG RD, JINHUI TOWN, FENGXI	AN SHANGHAI 201405 C	HINA

Sample Description	: JAC SIDE CLASSIC TIMBER CHAIR
Sample Receiving Date	: SEP. 17, 2019
Testing Period	: SEP. 17, 2019 TO SEP. 30, 2019
Test Performed	: SELECTED TEST(S) AS REQUESTED BY APPLICANT
Test Requested	: ANSI/BIFMA X5.1-2017: GENERAL-PURPOSE OFFICE
	CHAIR- AMERICAN NATIONAL STANDARD FOR
	OFFICE FURNITURE
Test Result(s)	: FOR FURTHER DETAILS, PLEASE REFER TO THE
	FOLLOWING PAGE(S)
Conclusion	: THE SUBMITTED SAMPLE MET THE TEST
	REQUIREMENT.

Signed for and on behalf of SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Melooly

Melody Zhang Authorized Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions, agr.and, for electronic format documents subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document taspx. Attention is drawn to the limitation or liability, indemnification and jurisdiction issues defined therein. Any holder of this document taspx. Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or results shown in this test report refer only to the sample(s) tested and such sample(s) are related for 30 days only. Attention: Check the authenticity of using inspection report a certificatie, please contact us at telephone: (86-75) 8307 1443, or email: CN.Doccheck@ags.VanDebind.Snaphal, China 200233 t (86) 400 960 9661 f (86-21) 6115 6899 www.sgsgroup.com.on

4" Building, No.889, Yishan Road, Xuhui Dishrid Shanghai, China 200233 t (86) 400 960 9661 f (86-21) 6115 6899 www.sgsgroup.com.cn 中国・上海・徐汇区宜山路889号4号楼 邮编: 200233 t (86) 400 960 9661 f (86-21) 6115 6899 e sgs.china@sgs.com



No.: SHHL1909051777FT

Date: SEP. 30, 2019 Page: 2 of 8

**Test Conducted:** 

**Test Report** 

ANSI/BIFMA X5.1-2017: General-Purpose Office Chair- American National Standard For Office Furniture

Testing Condition	:	All the physical test is carry out in indoor ambient.
Nos. of Specimen	:	3 pc(s).
Type of Chair	:	Таре Ш
Test Result	:	Pass

Test Property	Test Method	Test Principle / Requirements	Results
Back Strength Test -	ANSI/BIFMA	No loss of serviceability when 667 N	N/A
Static - Type I (Functional	X5.1 -2017 Clause 5	(150 lbs.) is applied for 1 min. Applied	See note 1
Load)		70° to the back at 16 in. above the seat.	
Back Strength Test-	ANSI/BIFMA	No sudden and major change in the	N/A
Static – Type I (Proof	X5.1 -2017 Clause 5	structural integrity (loss of serviceability	See note 1
Load)		is acceptable) when 1001 N (225 lbs.) is	
		applied for 1 min. Applied 70° to the	
		back at 16 in. above the seat.	
Back Strength Test -	ANSI/BIFMA	No loss of serviceability when 667 N	Pass
Static – Type II & III	X5.1 -2017 Clause 6	(150 lbs.) is applied for 1 min. Applied	
(Functional Load)		70° to the back at 16 in. above the seat.	_
Back Strength Test -	ANSI/BIFMA	No sudden and major change in the	Pass
Static – Type II & III	X5.1 -2017 Clause 6	structural integrity (loss of serviceability is	
(Proof Load)		acceptable) when 1001 N (250 lbs.) is	
		applied for 1 min. Applied 70° to the back	
		at 16 in. above the seat.	
Drop Test – Dynamic	ANSI/BIFMA	No loss of serviceability when 102kg	Pass
(Functional Load)	X5.1 -2017 Clause 7	(225 lbs.) weight free falls from 6 in	
		height to the center of the seat.	
Drop Test – Dynamic	ANSI/BIFMA	No sudden and major change in the	Pass
(Proof Load)	X5.1 -2017 Clause 7	structural integrity (loss of serviceability	
		is acceptable) when 136kg (300 lbs.)	
		weight free falls from 6 in height to the	
Quiting Tract Quality		center of the seat.	N1/A
Swivel Test – Cyclic	ANSI/BIFMA X5.1 -2017 Clause 8	No loss of serviceability after 60,000	N/A
	X5.1 -2017 Clause 8	cycles of rotation (360°) under a 122kg	See note 1
		(270 lbs.) load on the seat at its max.	
		height. Seat shall then withstand another 60,000 cycles of rotation at its lowest	
Tilt Mechanism Test –	ANSI/BIFMA	seating position. Total 120,000 cycles.	N/A
	X5.1 -2017 Clause 9	No loss of serviceability after 300,000	See note 1
Cyclic – Type I & II	A5.1-2017 Clause 9	cycles under a 109kg (240 lbs.) load to	See note 1
		the center of the seat	



Member of the SGS Group (SGS SA)

f (86-21) 6115 6899

www.sgsgroup.com.cn

e sgs.china@sgs.com



No.: SHHL1909051777FT

Date: SEP. 30, 2019

9 Page: 3 of 8

Test Property	Test Method	Test Principle / Requirements	Results
Impact test	ANSI/BIFMA X5.1 -2017 Clause 10.3	No loss of serviceability in 100,000 cycles impact. A weight of 57kg (125 lbs.) free falls onto the seat from 1.4 in. height.	Pass
Front Corner Load Ease Test – Cyclic – Off Center	ANSI/BIFMA X5.1 -2017 Clause 10.4	No loss of serviceability after load each seat front corner with 890N (200 lbs.) for 20,000 cycles, total 40,000 cycles. Note: this test is done after "Impact test" on the same sample.	Pass
Stability Test - Rear Stability for Type III Chairs	ANSI/BIFMA X5.1 -2017 Clause 11.3.1	<ul> <li>Load the chair with 6 disks, apply a horizontal force to the highest disk, The location of the force application is 6 mm (0.25 in.) from the top of the disk.</li> <li>For chairs with seat height less than 710 mm (28.0 in.), calculate the force as follows:</li> <li>F = 0.1964 (1195 – H) Newton. H is the seat height in mm.</li> <li>[F = 1.1 (47 – H) pounds force.]. H is the seat height in inches.</li> <li>For chairs with seat height equal to or greater than 710 mm (28.0 in.), a fixed force of 93 N (20.9 lbf.) shall be applied. The chair shall not tip over.</li> </ul>	Pass
Stability Test - Rear Stability for Type I and II Chairs	ANSI/BIFMA X5.1 -2017 Clause 11.3.2	Load the chair with 13 disks, place the first disk on the seat so it touches the support fixture. The chair shall not tip over.	N/A See note 1
Stability Test – Front Stability	ANSI/BIFMA X5.1 -2017 Clause 11.4	The chair is obstructed with a 13mm (½ in.) obstruction to the chair casters/legs. A downward load of 61kg (135 lbs.) is centered 60mm (2.4 in.) from the seat front center edge. The seat shall withstand a 20N (4.5 lbf.) horizontally from the front seat edge without tipping.	Pass
Arm Strength Test Vertical – Static (Functional Load)	ANSI/BIFMA X5.1 -2017 Clause 12	No loss of serviceability when 750N (169 lbs.) is applied for 1 min. The vertical load is uniformly applied along a 127mm (5 in.) length at the apparent weakest point.	N/A See note 1
Arm Strength Test Vertical –Static (Proof Load)	ANSI/BIFMA X5.1 -2017 Clause 12	No sudden and major change in the structural integrity (loss of serviceability is acceptable) when 1125N (253 lbs.) is applied for 15 seconds. The vertical load is uniformly applied along a 127mm (5 in.) length at the apparent weakest point.	N/A See note 1





No.: SHHL1909051777FT

Date: SEP. 30, 2019

9 Page: 4 of 8

Test Property	Test Method	Test Principle / Requirements	Results
Arm Strength Test	ANSI/BIFMA	No loss of serviceability when 445N (100	N/A
Horizontal – Static	X5.1 -2017 Clause	lbs.) for 1 min. is applied horizontally	See note 1
(Functional Load)	13	outward to the armrest at the most	
		forward point of the armrest.	N1/A
Arm Strength Test Horizontal – Static	ANSI/BIFMA X5.1 -2017 Clause	No sudden and major change in the	N/A See note 1
(Proof Load)	13	structural integrity (loss of serviceability is acceptable) when 667N (150 lbs.) for	See note 1
	15	15 seconds. is applied horizontally	
		outward to the armrest at the most	
		forward point of the armrest.	
Back Durability Test -	ANSI/BIFMA X5.1 -	No loss of serviceability in 120,000	N/A
Cyclic – Type I	2017 Clause 14	cycles with a 109kg (240 lbs.) in the	See note 1
		center of the seat and a 445N (100 lbf.)	
		90° to the center of the chair back. For	
		chairs with a back width greater than	
		406mm (16 in.), test at the center of	
		chair back for 80,000 cycles and then	
		102mm (4 in.) off-center 40,000 cycles, half to each side.	
Back Durability Test –	ANSI/BIFMA X5.1 –	No loss of serviceability in 120,000	Pass
Cyclic – Type II & III	2017 Clause 15	cycles with a 109kg (240 lbs.) in the	1 400
		center of the seat and a 334N (75 lbf.)	
		90° to the center of the chair back. For	
		chairs with a back width greater than	
		406mm (16 in.), test at the center of	
		chair back for 80,000 cycles and then	
		102mm (4 in.) off-center 40,000 cycles,	
Castar / Chair Basa	ANSI/BIFMA X5.1 -	half to each side.	N/A
Caster / Chair Base Durability Test For	2017 Clause 16.1	No loss of service after 2,000 cycles over a hard surface with 3 obstacles and	See note 1
Pedestal Base Chair	2017 Clause 10.1	98, 000 cycles over a smooth hard	
		surface without obstacles under a 122kg	
		(270 lbs.) load on the seat. Test stroke is	
		762mm (30 in.) minimum. The caster	
		should not separate under 22N (5 lbs.)	
		pulling force in line with the caster stem	
		after the cycling test.	
Caster / Chair Base	ANSI/BIFMA X5.1 -	No loss of service after 2,000 cycles	N/A
Durability Test For	2017 Clause 16.2	over a hard surface with 2 obstacles and	See note 1
Chairs with Legs		98, 000 cycles over a smooth hard surface without obstacles under a 122kg	
		(270 lbs.) load on the seat. Test stroke is	
		762mm (30 in.) minimum. The caster	
		should not separate under 22N (5 lbs.)	
		pulling force in line with the caster stem	
		after the cycling test.	





No.: SHHL1909051777FT

77FT Date: S

Date: SEP. 30, 2019 F

9 Page: 5 of 8

Test Property	Test Method	Test Principle / Requirements	Results
Leg Strength Test – Front Load (Functional Load)	ANSI/BIFMA X5.1 - 2017 Clause 17.3	No loss of serviceability when a force of 334N (75 lbf.) is applied to each front leg individually for 1 minute.	Pass
Leg Strength Test – Front Load (Proof Load)	ANSI/BIFMA X5.1 - 2017 Clause 17.3	No sudden and major change in the structural integrity (loss of serviceability is acceptable) when a force of 503N (113 lbf.) is applied to each front leg individually for 1 minute.	Pass
Leg Strength Test – Side Load (Functional Load)	ANSI/BIFMA X5.1 - 2017 Clause 17.4	No loss of serviceability when a force of 334N (75 lbf.) is applied once to each front and rear leg individually for 1 minute.	Pass
Leg Strength Test – Side Load (Proof Load)	ANSI/BIFMA X5.1 - 2017 Clause 17.4	No sudden and major change in the structural integrity (loss of serviceability is acceptable) when a force of 503N (113 lbf.) is applied once to the front and rear leg individually for 1 minute.	Pass
Footrest Static Load Test – Vertical- Functional load (lf applicable)	ANSI/BIFMA X5.1 - 2017 Clause 18.4.1	Apply a force F1 of 445 N (100 lbf.) uniformly along a 102 mm (4 in.) distance along the footrest but not greater than 51 mm (2 in.) from the outside edge at the apparent weakest point of the structure for one (1) minute in the vertical downward direction, maintain force F1 and apply an additional force F2 of 445 N (100 lbf.) to the footrest at the opposing position for an additional one (1) minute. There shall be no loss of serviceability or sudden loss of footrest height.	N/A See note 1
Footrest Static Load Test – Vertical-Proof load (If applicable)	ANSI/BIFMA X5.1 - 2017 Clause 18.4.3	Apply a force of 1334 N (300 lbf.) uniformly along a 102 mm (4 in.) distance along the footrest but not greater than 51 mm (2 in.) from the outside edge at the apparent weakest point of the structure for one (1) minute in the vertical downward direction. The load applied once shall cause no sudden and major change in the structural integrity of the unit. Loss of serviceability is acceptable.	N/A See note 1
Footrest Durability Test – Vertical – Cyclic (If applicable)	ANSI/BIFMA X5.1 - 2017 Clause 19	No loss of serviceability after 50,000 cycles of a 890N (200 lbf) load vertical along 102mm (4 in.) length of the footrest at the apparent weakest point of the structure.	N/A See note 1





No.: SHHL1909051777FT

Date: SEP. 30, 2019

Page: 6 of 8

Test Property	Test Method	Test Principle / Requirements	Results
Arm Durability Test – Cyclic	ANSI/BIFMA X5.1 - 2017 Clause 20	No structural breakage or loss of serviceability when a force of 400N (90 lbf.) is applied to each arm at a $10^{\circ}$ angle $\pm 1^{\circ}$ for 60,000 cycles	N/A See note 1
Out Stop Tests For Chairs With Manually Adjustable Seat Depth (If applicable)	ANSI/BIFMA X5.1 - 2017 Clause 21	Place 74 kg (163 lb.) rigid mass in the center of the seat, 25 kg (55lbf.) hanging weight shall be held at its most rearward position, then released, permitting it to move forward rapidly and impact the out stops. Repeat for a total of 25 cycles. There shall be no loss of serviceability to the unit.	N/A See note 1
Tablet Arm Static Load Test (If applicable)	ANSI/BIFMA X5.1 - 2017 Clause 22	Apply a load of 68 kg (150 lb.) through a 203 mm diameter area 25 mm from the edge of the surface at its apparent weakest point, for one (1) minutes. Shall cause no sudden and major change in the structural integrity of the chair at the first load, and after performing the test, the tablet arm must allow egress form the unit; other losses of serviceability are acceptable.	N/A See note 1
Tablet Arm Load Ease Test – Cyclic (If applicable)	ANSI/BIFMA X5.1 - 2017 Clause 23	A 25kg (55 lb.) bag shall be raised until the entire weight is off the tablet surface and then eased (without impact) onto the surface, repeat for a total of 100,000 cycles without loss of serviceability to the unit.	N/A See note 1
Structural Durability Test – Cyclic	ANSI/BIFMA X5.1 - 2017 Clause 24	Place a weight of 109kg (240lbf) in the center of the seat. Apply a force of 334N (75lbf) at an appropriate for 25000cycles by a cycling device. There shall be no loss of serviceability	Pass
Informative - Base Test – Static	ANSI/BIFMA X5.1 -2017 Appendix C	No sudden and major change in the structural integrity under 11,120 N (2500 lbs.) compression for 1 min. The weight is then removed and reapplied for 1 min. The center column may not touch the test platform during load applications.	N/A See note 1





No.: SHHL1909051777FT

Date: SEP. 30, 2019

Page: 7 of 8

Test Property	Test Method	Test Principle / Requirements	Results
Informative – Simultaneous side legs strength test	ANSI/BIFMA X5.1 -2017 Appendix H	The chair shall be placed on a test platform with the side legs restrained by a block 11 to 38mm high. All adjustments shall be set at normal use conditions. A force of 334N (75lbs.) per leg shall be applied once to a front and rear leg simultaneous for one minute. Remove force, there shall be no loss of serviceability.	Pass

Note N/A means not applicable to this product design. # 1-

### Remark:

- 1. Since the data and / or information above division line of front page is provided by the applicant, the relevant results or conclusions of this report are only made for these data and / or information, SGS is not responsible for the authenticity, integrity and results of the data and information and / or the validity of the conclusion. Testing results only apply to the sample as received.
- 2. The declaration of conformity is only based on the actual value of laboratory activity, measurement uncertainty of the results not take into account.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document. This document cannot be reproduced transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written apporval of the Company. Any unauthorized alteration, forgery or falsification of the content or appoarance of this document is unlawful and effenders may be proscued to the fullect extent of the law. Unloce otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,

4th Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 t (86) 400 960 9661 f (86-21) 6115 6899 www.sgsgroup.com.cn 中国・上海・徐汇区宜山路889号4号楼 邮编: 200233 t (86) 400 960 9661 e sgs.china@sgs.com f (86-21) 6115 6899



### No.: SHHL1909051777FT Date: SEP. 30, 2019

P. 30, 2019 Page: 8 of 8

Sample Photo:

Received sample view 1



Received sample view 2



SGS authenticate the photo on original report only

\*\*\*End of Report\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions, agrx and, for electronic format documents as subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Conditio

t (86) 400 960 9661 f (86-21) 6115 6899 e sgs.china@sgs.com Member of the SGS Group (SGS SA)